

96/30

November 20 1893
021886

SEARS AVE.

40

40

216.31

50

40

CAMBRIDGE ST.

RANGELEY AVE.

The lines of Rockland ave are correct as shown.

The lines of Rangeley ave are made to agree with the stone bounds but do not agree with the distances given on the "Replat of the Bowen Plat" and are approximate.

See Plat #3 made by R.S. Mowry Oct. 1895.

101.41 ±
6.6.f. on line on line
5.8. (non removed) on line

6.6.4.94 off
4.88 off
6.6.4.98 off

6.6.f. 0.59 on 0.7500

6.6.6.22 off
6.04 off
6.6.6.22 off

6.6.5.99 off
5.89 off

329.16

6.6.8.61 off
7.91 off
6.6.8.35 off

6.6.7.67 off
6.83 off
6.6.6.36 off

6.6.f. on line 12.0.
6.6.f. on line 8.574 off
6.6.f. on line 0.45

295.65
294.56

89° 44' 20"
89° 33'

40

ROCKLAND

96/30
6.6.7.60